

Menu

HISTORY FILE MAP for year 2008

REALTIME


PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

039.10:25-15:25 5hrs of realtime 1024 bps INT telemetry lost due to DSS-63 power failure. Data loss results in 13hrs 20mins of 128 bps recorded data being lost. DR M104659 refers.

036.22:16-23:20 1hr 4 mins of realtime 128 bps telemetry lost on DSS-24 due to suspected RFI. DR G108326 refers.



037.08:01-08:22 21mins of recorded 128 bps telemetry lost due to data hit during playback on DSS-63. No DR.

037.09:52-11:56 2hr 4 mins of realtime 128 bps telemetry intermittant on DSS-24 due to low elevation. No DR.

041.03:54-04:19 25mins of realtime 128 bps telemetry lost on DSS-24 due to low elevation. No DR.

041.18:05-18:28 23mins of recorded 128 bps telemetry lost due to data hit during playback on DSS-63. No DR.

041.19:37-20:06 29mins of recorded 128 bps telemetry lost due to data hit during playback on DSS-63. No DR.

042.07:16-07:38 22mins of recorded 128 bps telemetry lost due to data hit during playback on DSS-63. No DR.

038.03:22-04:18 56 mins of realtime 128 bps telemetry intermittant on DSS-24 due to low elevation. No DR.

038.10:03-10:32 29mins of recorded 128 bps telemetry lost due to data hit during playback on DSS-63. No DR.

039.06:44-07:10 26mins of recorded 128 bps telemetry lost due to data hit during playback on DSS-63. No DR.

039.23:14-23:40 26mins of recorded 128 bps telemetry lost due to data hit during playback on DSS-63. No DR.

040.00:35-01:18 43mins of realtime 128 bps telemetry lost on DSS-24. Telemetry resumed after predicts disabled and receiver reset. DR G108332 refers.